# R7184U Interrupted Electronic Oil Primary Honeywell





Make one-stop service calls with the Honeywell R7184U electronic oil primary. The Honeywell R7184U is a universal control that replaces multiple controls, provides upgrade opportunities and is EnviraCOM™-enabled. Stock fewer models, simplify service calls with built-in diagnostics, satisfy your customers and increase revenue with the industry's best choice for oil burner service work.

## **R7184U Interrupted Electronic Oil Primary**



### Ready To Roll

Honeywell has designed the R7184U for easy installation and operation in both hydronic and forced-air systems. The state-of-the-art features of this oil primary make this control truly universal, replacing all others on your truck.

#### Features:

- Interrupted ignition
- · Limited reset and recycle
- Diagnostic LED
- · Pump priming cycle
- Displays cad cell resistance
- · Valve-on and blower motor-off delay
- Disable function
- EnviraCOM<sup>™</sup>-enabled
- Alarm contacts

#### EnviraCOM™


All Honeywell R7184U oil primaries are EnviraCOM-enabled. EnviraCOM is a low-cost 3-wire communication protocol that allows different devices — such as EnviraCOM communicating thermostats,

#### **Automation and Control Solutions**

In the U.S.:

Honeywell 1985 Douglas Drive North Golden Valley, MN 55422-3992

In Canada: Honeywell Limited 35 Dynamic Drive Toronto, Ontario M1V 4Z9 1-800-345-6770, ext. 423 www.honeywell.com aquastats and oil primaries — to connect and share information. So, whether you're replacing old controls or installing new equipment, those customers are ready for Honeywell EnviraLINK $^{\text{\tiny{M}}}$  – a communication and remote diagnostic service that links your customers' equipment with your office.



#### Truly Universal

Brand	OS#	Safety Switch Timing (seconds)	Valve On Delay	Burner Motor Off Delay (seconds)	Alarm
Honeywell	R7184U1004	15	0 or 15	0 or 0/120/240/360	Yes
Replaces					
Carlin	40200-02S	15	0	0	No
Carlin	50200-02S	15	0	0	Yes
Carlin	602000-2S	15	10	10	Yes
Carlin	6020002S015120	15	15	120	Yes
Carlin	6020002S030015	15	30	15	Yes
Carlin	6020002S030030	15	30	30	Yes
Carlin	6020002S030120	15	30	120	Yes
Carlin	6020002S030300	15	30	300	Yes
Carlin	6020002S060010	15	60	10	Yes
White-Rodgers	669-640	15	No	No	No
White-Rodgers	669-670	15	No	No	Yes

Brand	OS#	Safety Switch Timing (seconds)	Valve On Delay	Burner Motor Off Delay (seconds)	Alarm
Honeywell	R7184U1012	30	0 or 15	0 or 0/120/240/360	Yes
Replaces					
Carlin	42230-02S	30	0	0	No
White-Rodgers	669-440	46	No	No	No
White-Rodgers	669-445	46	No	No	No
White-Rodgers	669-470	45	No	No	Yes
White-Rodgers	669-540	30	No	No	No

#### Learn More

For more information about putting the R7184U to work for your company, visit your Honeywell distributor, call 1-800-345-6770, ext. 423, or visit customer.honeywell.com.

